

CURRENT IN AMPERES X100

FORM 480 AMP-TRAP FUSE
MELTING TIME-CURRENT DATA
400-6000 amps. 600 VOLT
CAT. NO. A4BX (AMP. RATING)

GOULD INC., ELECTRIC FUSE DIV.
NEWBURYPORT, MA. 01950

07028C

